

Division of Oil, Gas, & Mining
Mining Report

03/08/95

MINE ID: S0550011

MINE NAME: LUCKY JOHN #1-4

OPERATOR: OSBORN, JOHN R
CONTACT: JOHN R. OSBORN
ADDRESS: PO BOX 502
ROMEO CO 81148

PHONE: (303)843-5689

Surface Owner: BLM
Mineral Owner: BLM

BLM #: UTU-71609
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
	NW	SE				18	30.0S	6.0E

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status: SUS

Acreage: 1

Status Date: / /

Minerals Mined
??

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

06/07/93

/ /

06/22/93

/ /

BOND TYPE:

BOND AMOUNT:

ANNUAL REPORT YEAR: 94

	YTD	Total					
NONCOMP NOTICES:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
VIOLATIONS:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	/
REVISIONS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/
AMENDMENTS:	0	0	DATE REC'D:	/	/	DATE APPROVED:	/

COMMENTS:

BLM LEAD & COPIED DOGM ON THIS NOI. INITIAL OPERATION WILL INVOLVE USE OF BACK-HOE & LOADER TO MINE ALONG MINERS MTN ROAD. IF MINERALIZATION WARRANTS, BULL-DOZER WILL BE USED TO OPEN UP DEPOSIT. RECLAMATION WILL BE DONE TO STABILIZE WHERE POSSIBLE.